

INSTALLATION MANUAL

571720

Mega/Omega Step Bracket kit 2015+ Ford Transit Van Long\Long

Parts List 3 Front Mounting Bracket AC Mounting Bracket AC Top Mounting Bracket 3 U-Bolt 3" 6 Bolt Retainer 10 Lock Washer, 5/16 Flange Nut M8 10 Hex Bolt, M8 Thread Cutting Bolt 5/16 Washer,5/16 Clip Nut M8

Level of Difficulty

Easy

Product Image



Front Mounting Bracket (553204)



AC Mounting Bracket (553211)



AC Top Mounting Bracket (553212)

Notes and Maintenance

Before you begin installation, read all instructions thoroughly.

Make sure all required parts are on hand before starting the installation.

Tools Required		
Socket, 1/2"	Ratchet	
Wrench, 1/2"	Drill	
Flat Screwdriver	Drill Bit, 3/8"	
Marker	Drill Bit, 3/32	
Putty Knife	Drill Bit, 19/64	

Step 1

Starting on the Passanger side, locate mounting locations as shown in Fig 1 and Fig 3.

Hold each bracket in its mounting locations and mark each hole on the rocker and pinch weld.







Step 2

From the under side of the plastic rocker molding use a flat head screw drive to release the bottom push pins.


NOTE: Do not remove plastic trim all the way only release the bottom push pins.



Step 3

Starting on the first bracket using a 3/32" drill bit, drill a pilot hole In each of the marked spots followed by a 3/8" drill bit.

NOTE: Place a Putty knife between the pinch weld and the plastic rocker molding to avoid damaging molding from drilling.



Step 4





Using the 3" U-Bolt put it through the top 2 mounting holes and secure with (2) plastic bolt retainer.

Slide (2) Clip Nuts on the pinch weld for the bottom mounting locations.

Slide the front mounting bracket on the U-Bolts and secure with (2) 5/16 flat washers (2) 8mm nuts on the studs, and (2) 5/16 lock washer and (2) 8mm bolts in the clip nuts.

Leave all brackets loose untill the end.

Repeat for 2nd bracket

Step 5

Moving to the driver side, locate monting locations using Fig 2 and Fig 4.



Step 6





Repeat stesp 1-4 for installing the **front driver side bracket.**

Step 7

Assemble the AC bracket using the (2) M8 Bolts, (2) 5/16 washers, (2) M8 nuts.



Step 8



After assembling the AC bracket place along the pinch seam using Fig. 2 and Fig. 4 marking the 4 hole locations

Drill the 2 upper holes with a 19/64 drill bit and the bottom 2 with a 3/8 drill bit

NOTE: THE 2 TOP HOLES WILL USE SELF THREADING BOLTS.





Step 10



Slide 2 clip nuts on the pinch weld for lower holes attache the AC bracket using (2) 8MM Bolts and (2) 5/16 Lock Washers on the bottom Clip Nuts and (2) 5/16 Thread Cutting Bolt and (2) 5/16 lock washers on the upper holes

Step 11


Leave ALL brackets Loose at this time. Please Review the installation instructions that are included in your step assembly for specific details. Place step board on brackets tighten all brackets so the board is level.


PARTS LIST FOR MOUNTING 571720 MEGA STEP BRACKETS 2015 AND NEWER FORD TRANSIT VAN

SERVICE PARTS LIST

ITEM	PART NO.	QTY	DESCRIPTION
1	553204	3	FRONT MOUNTING BRACKET
2	553211	1	AC MOUNTING BRACKET
3	553212	1	AC TOP MOUNTING BRACKET
4	101795	3	U-BOLT 3.00
5	101572	6	BOLT RETAINER
6	100030	10	5/16 LOCK WASHER
7	100034	8	5/16 WASHER
8	105859	10	M8 FLANGE NUT
9	102549	10	M8 HEX BOLT
10	101566	8	M8 CLIP NUT
11	109177	2	5/16 THREAD CUTTING BOLT








SERVICE PARTS LIST

BRACKET NO. 571720

-RIGHT (PASSENGER) SIDE SHOWN-





SERVICE PARTS TSII

BRACKET NO. -571720

-LEFT (DRIVERS) SIDE SHOWN-

NOTE:
THESE DIMENSIONS MAY NEED TO BE ADJUSTED FORWARD, OR BACKWARD
TO AVOID DRILLING THROUGH SPOT WELDS IN THE PINCH SEAM.

