

HRDD5G**HONDA**
Rear suspension package
Ensemble pour suspension arrière
Ensemble para suspensión de trasero
INSTALLATION INSTRUCTIONS

- Raise vehicle allowing the axle to hang freely.
- Remove existing bump stop by prying out of bump stop cup.
- Position Timbren spring assembly into bump stop cup. Use soapy water if required. (To ensure that the Aeon assembly is properly seated in the cup, it will help to place a temporary spacer such as a short piece of 2x4 wood between the frame and the Aeon assembly.
- Lower vehicle.

NOTE:

Ensure Timbren assembly is properly seated in bump stop cup.

Do not exceed vehicle manufacturer's recommended axle weight rating. Check for AEON® interference with vehicle components - Under load AEON® will "expand" in diameter.

INSTRUCTIONS DE MONTAGE

- Soulever le véhicule de sorte que l'essieu soit dégagé.
- Retirer la butée de suspension existante en insérant un levier dans l'échancrure de la butée de suspension.
- Placez l'ensemble de ressorts Timbren dans la coupelle de butée. Utilisez de l'eau savonneuse si nécessaire. (Pour que l'assemblage Aeon soit correctement installé dans la coupelle, il est utile de placer une entretoise temporaire telle qu'un court morceau de bois 2x4 entre l'essieu et l'ensemble Aeon.
- Redescendre le véhicule.

NOTE:

S'assurer que l'assemblage Timbren soit convenablement placé dans l'échancrure de la butée de suspension.

Ne pas dépasser le poids nominal sur l'essieu recommandé par le fabricant du véhicule. Vérifier que le ressort AEON® n'a pas d'incidence sur d'autres pièces du véhicule - Le ressort AEON® augmentera son diamètre avec la charge.

INSTRUCCIONES DE INSTALACIÓN

- Levante el vehículo dejando que los ejes cuelguen libremente.
- Retire el tope de suspensión existente haciendo palanca en la copa del tope de retención.
- Coloque el ensamble del resorte Timbren en la taza de tope de tope. Use agua jabonosa si es necesario. (Para asegurarse de que el ensamble Aeon esté correctamente asentado en la taza, ayudará a colocar un espaciador temporal, como una pieza corta de madera de 2x4 entre el eje y el ensamble Aeon.
- Baje el vehículo.


NOTE:

Asegúrese de que la unidad Timbren está correctamente encajado en la copa del tope de retención.

No exceda la carga nominal en el eje recomendada por el fabricante del vehículo. Compruebe que no haya interferencia entre el resorte AEON® y los otros componentes del vehículo. Bajo carga, el resorte AEON® se ampliará en diámetro.

Ref. = Reference = No. de référence = Núm. de referencia
Part = Part #. = No. de pièce = Núm. de pieza
Qty. = Quantity = Quantité = Cantidad

Ref	Part	Qty
1	A00525-65AG00	2
2	A16250-003	2
3	A25792-75P20	2
4	F11538-350	2

KIT PRE-ASSEMBLED BY TIMBREN.**HRDD5G**

PART NUMBER	DESCRIPTION	QTY	LOCATION
F11538-350	HCS M10 x 40 x 1.5 Gr. 8.8 Z	2	I1C
A00525-65AG00	HOLLOW RUBBER SPRING	2	C4D
A25792-75P20	AEON LOCATOR	2	TBD
A16250-003	DISC 2-1/2 OD x 13/32 ID x 3/16 THK	2	E(END)A
B90200-CR	SMALL REAR BOX - 9.5 x 7 x 5.5	1	A--E
B10000	8" X 12" BUBBLE FOR KITS	1	
B00029-010	BARCODE LABEL FOR KIT	1	

ASSEMBLY NOTES:

PRE-ASSEMBLED KIT

Issued: 02/27/2020

Clearance Instructions:

Rear SES Kits for Pick-Ups and Vans should have a 1/2" to 1-1/2" gap between the rubber spring and contact point when empty.

A partial load, or vehicle accessories will reduce or eliminate the gap.

Front SES kits are usually in full contact.

Medium and Heavy-Duty Trucks, Trailers and Motorhomes will be in constant contact, and have no gap.

Lifetime Warranty:

Timbren SES Kits are warranted against defects in material and workmanship, under normal use and service, for the life of the vehicle on which the kit was originally installed. The warranty is not transferable and proof of purchase is required. The warranty is limited to the replacement of the failed part.

TIMBREN will not be responsible for any labour or freight charges involved in the replacement of any product. TIMBREN shall be entitled to make its own inspection to determine the validity of the claim. TIMBREN shall not be liable nor warranty the product in the event of alteration, misuse, overload, negligence or damage caused by others.

If ride or performance of our product is unsatisfactory in any way, please call: 1-800-263-3113 or email sales@timbren.com